

# Tip of the month – January 2016

## Better milking good udders

You might sometimes notice that the VMS has trouble attaching the liners to a cow with a good udder and good teat placement.

It is quite probable that something went wrong during the last milking which resulted in saving the wrong teat positions.

Simply one more time teaching the cow again is the best advice.

Ensure that the grippers are perfectly under the teat.

And where the laser once was calibrated halfway on the teat, it must now be adjusted at the **lower tip of the teat!**